





# SERVICE BULLETIN

PUBLICATION GROUP, AFTER SALES SERVICE DEP.  
MITSUBISHI MOTOR SALES EUROPE BV

<b>SERVICE BULLETIN</b>		No.: ESB-99E42-504																					
		Date: 1999-11-15	<Model> (EC,EXP) CARISMA <M/Y> 98-10																				
Subject: CORRECTION TO CENTER DOOR LOCK TROUBLESHOOTING																							
Group: BODY																							
CORRECTION	 O. Kai - E.V.P. & G.M. After Sales Service Dept.																						
<b>1. Description:</b> This Service Bulletin informs you that typographical errors in the center door lock troubleshooting have been rectified.																							
<b>2. Applicable Manuals:</b> <table border="1"> <thead> <tr> <th>Manual</th> <th>Pub. No.</th> <th>Language</th> <th>Page(s)</th> </tr> </thead> <tbody> <tr> <td rowspan="7">'98 CARISMA Workshop Manual chassis</td> <td>PWDE9502-B</td> <td>(English)</td> <td rowspan="7">42-5</td> </tr> <tr> <td>PWDS9503-B</td> <td>(Spanish)</td> </tr> <tr> <td>PWDF9504-B</td> <td>(French)</td> </tr> <tr> <td>PWDG9505-B</td> <td>(German)</td> </tr> <tr> <td>PWDD9506-B</td> <td>(Dutch)</td> </tr> <tr> <td>PWDW9507-B</td> <td>(Swedish)</td> </tr> <tr> <td>PWDI96E1-B</td> <td>(Italian)</td> </tr> </tbody> </table>				Manual	Pub. No.	Language	Page(s)	'98 CARISMA Workshop Manual chassis	PWDE9502-B	(English)	42-5	PWDS9503-B	(Spanish)	PWDF9504-B	(French)	PWDG9505-B	(German)	PWDD9506-B	(Dutch)	PWDW9507-B	(Swedish)	PWDI96E1-B	(Italian)
Manual	Pub. No.	Language	Page(s)																				
'98 CARISMA Workshop Manual chassis	PWDE9502-B	(English)	42-5																				
	PWDS9503-B	(Spanish)																					
	PWDF9504-B	(French)																					
	PWDG9505-B	(German)																					
	PWDD9506-B	(Dutch)																					
	PWDW9507-B	(Swedish)																					
	PWDI96E1-B	(Italian)																					
<b>3. Details:</b>																							

## Inspection Procedure 13

Some doors do not lock or unlock	Probable cause
The door lock actuator, a harness or connector may be defective.	<ul style="list-style-type: none"> <li>Malfunction of the door lock actuator</li> <li>Malfunction of the wiring harness or connector</li> </ul>



## NOTE

\*<sup>1</sup>: Refer to '96 CARISMA Workshop Manual (Pub. No. PWDE9502).

\*<sup>2</sup>: Refer to '97 CARISMA Workshop Manual (Pub. No. PWDE9502-A).