

Service Bulletin List

NR.	Subject	Date
ESB-96E11-502	OMISSION OF TIGHTENING TORQUE OF A/C COMPRESSOR TENSION PULLEY FIXING BOLT	1997-03-31
ESB-96E13-501	CORRECTION OF FUEL GAUGE UNIT INSTALLATION PROCEDURE	1996-05-15
ESB-96E13-506	CORRECTION TO PROCEDURE FOR EVACUATION OF WATER FROM THE FUEL FILTER	1997-02-28
ESB-96E35-001	FRONT BRAKE DISASSEMBLY AND REASSEMBLY PROCEDURES	1997-02-28
ESB-96E37-002	CHANGE OF POWER STEERING RETURN HOSE AND BOLT TIGHTENING TORQUES	1996-07-30
ESB-96E42-503	PROCEDURE FOR RESETTNG KEYLESS ENTRY RE CEIVER ECU	1997-02-28
ESB-96E52-001	ESTABLISHMENT OF REAR SEATBACK COVER REPLACEMENT PROCEDURE	1996-05-15
ESB-96E54-502	ADDITION OF CONTINUITY CHECKING PROCEDURE FOR SPEEDOMETER REED SWITCH	1997-03-31
ESB-96E55-502	ADDITION TO AIR PURIFIER TROUBLE-SHOOTING SECTION	1997-02-28
ESB-97E00-502	CORRECTION TO TIGHTENING TORQUE INDICATION	1997-01-15
ESB-97E11-503	CORRECTING VALVE CLEARANCE & INJECTION TIMING INSPECTION & ADJUSTMENT PROCEDURE	1997-11-24
ESB-97E13-002	CORRECTION TO ENGINE CONTROL SYSTEM DESCRIPTIONS	1998-02-28
ESB-97E13-501	CHANGES IN VEHICLE SPEED SENSOR AND IN ENGINE-ECU TERMINAL VOLTAGE	1997-03-15

Service Bulletin List

NR.	Subject	Date
ESB-97E13-506	CORRECTION TO TIGHTENING TORQUES OF FUEL TANK BAND NUTS	1998-03-31
ESB-97E17-001	CHANGE IN ERASURE OF CRUISE CONTROL SYSTEM DIAGNOSTIC TROUBLE CODES	1997-09-26
ESB-97E22-502	CORRECTION TO TRANSMISSION GEAR RATIOS AND TO TIGHTENING TORQUES	1999-07-15
ESB-97E22-503	CORRECTION TO GEAR RATIO AND FINAL REDUCTION RATIO FOR MANUAL TRANSMISSION	1997-12-05
ESB-97E22-504	CORRECTION TO TIGHTENING TORQUES FOR FILLER AND DRAIN PLUGS	1997-12-05
ESB-97E35-006	CHANGE IN LIMIT VALUE FOR FRONT BRAKE DISC RUN-OUT	1998-03-15
ESB-97E37-501	POWER STEERING OIL PUMP PRESSURE TEST NEEDED BY AVAILABILITY OF SPECIAL TOOLS	1997-09-26
ESB-97E51-501	CENTER CONSOLE PANEL AND CUP HOLDER REMOVAL	1998-03-15
ESB-97E52-002	ADDITION OF SRS AIR BAG MAINTENANCE PROCEDURE	1997-01-30
ESB-97E52-502	CORRECTION TO CAUTION ON AIR BAG MODULE AND CLOCK SPRING	1997-09-26
ESB-97E54-503	CLOCK REMOVAL AND INSTALLATION	1997-09-26
ESB-97E55-002	CHANGE IN AIR GAP FOR A/C COMPRESSOR	1998-03-15
ESB-97E55-003	CORRECTION TO AIR CONDITIONER PERFORMANCE TEST PROCEDURE	1998-03-15
ESB-98E00-014	CHANGE IN TIGHTENING TORQUE FOR TENSIONER PULLEY MOUNTING NUT	30-09-1999
ESB-98E13-001	CORRECTION OF '98 CARISMA GDI WORKSHOP MANUAL GROUP 13J	1998-05-31

Service Bulletin List

NR.	Subject	Date
ESB-98E13-001REV	CORRECTION OF '98 CARISMA GDI WORKSHOP MANUAL GROUP 13J	1998-12-15
ESB-98E13-002	CHANGES IN TROUBLESHOOTING	1998-12-15
ESB-98E16-001	CHANGE OF SPARK PLUG FROM PLATINUM TO IRIIDIUM PLUG	1998-10-15
ESB-98E16-501	CORRECTION TO DESCRIPTIONS OF IGNITION COIL (SECONDARY COIL)	1999-06-15
ESB-98E23-501	ADDITION / CORRECTION OF HYDRAULIC PRESSURE TEST OF AUTOMATIC TRANSMISSION	1999-06-15
ESB-98E26-001	ADDITION OF DRIVE SHAFT DISASSEMBLY/REASSEMBLY PROCEDURES	1998-02-15
ESB-99E21-501	CORRECTION TO CLUTCH PEDAL HEIGHT	1999-12-15
ESB-99E33-501	CORRECTION TO FRONT SUSPENSION CAMBER AND CASTER VALUES	1999-11-15
ESB-99E35-001	CHANGE TO LIMIT OF FRONT BRAKE DISC THICKNESS	1999-08-31
ESB-99E35-505	ADDITION OF DIAGNOSTIC TROUBLE CODE NO.15	2000-07-15
ESB-99E35-506	ADDITION OF CAUTION ON READING OF DIAGNOSTIC TROUBLE CODES	2000-04-15
ESB-99E37-001	CHANGE TO POWER STEERING OIL PUMP	1999-12-30
ESB-99E42-504	CORRECTION TO CENTER DOOR LOCK TROUBLESHOOTING	1999-11-15
ESB-99E51-001	ADDITION OF WASHER MOTOR REMOVAL	1999-12-15

Service Bulletin List

NR.	Subject	Date
MSB-97E11-502	CHANGE IN LASH ADJUSTER CHECKING PROCEDURE	1997-02-28
MSB-97E11-503REV	INSPECTION & ADJUSTEMENT PROCEDURE FOR VALUE CLEARANCE & INJECTION TIMING	1997-06-15
MSB-97E16-001	CHANGE IN ALTERNATOR OUTPUT CURRENT	1997-01-15
MSB-98E52-502	CORRECTION TO ERASING OF DIAGNOSIS CODES	1999-10-31